LEGEND

TAPE MEASURE ATTACHMENT

- 10 Measuring tape
- 12 Edges of measuring tape
- 14 Leading end of measuring tape
- 16 Tab at leading end
- 18 Workpiece to be measured
- 20 Apparatus for attachment to measuring tape
- 30 Workpiece engagement means
- 32 Rigid engagement member
- 34 Top of engagement member
- 36 Bottom of engagement member
- 38 Front face of engagement member
- 40 Rear face of engagement member
- 42 Surface for engaging workpiece
- 44 Projection from engagement member
- 46 Indentation for receiving measuring tape tab
- 50 Attachment means
- 52 Rigid attachment member
- 54 Rigid attachment tabs
- 56 Kerf